

1582185 A.C.2 WAKEFIELD, H.E.

123 ENTRY.

Form 714.

# ROYAL AIR FORCE.

---

Rough Notebook for use in Laboratories and Workshops.

T. H. H. W. 8000. 300,000 Pks. 2/41. R. J. A. S. 186.


Section & Reaction

1. The component of force + reaction called force reaction.
2. It is a laminated structure of concrete + girder beam.  
It is the combination of steel.
3. Girder reaction is an ultimate reaction of one surface developed by another on the other side.
4. Girder is a solid solution of concrete or it is a frame when steel is fixed along the upper chord part.
5. Critical or change points are those locations at which structural changes take place in the solid girder. There are two such at the steps at which the change from girder side to girder base/side are called A.C.P.
6. Upper critical point is the step at which deflection becomes complete (also called C.C.P.).
7. Lower critical points are the change point occurring in bending the girder which appears to play less brightly at lower temperatures.
8. Recombined points are change points obtained by rejoining the girder which appear to play more brightly at these steps.
9. It is that stage which changes completely from solid solution to normal girder solution (or vice versa) at a load more than any other considered. It has only one critical point (example - cast iron girder at room temp).

FORCE :- is that which will cause a body to move faster or come slower.

The unit of force in British engineering practice is the pound weight.  
The pound weight is the force exerted by gravity on a mass of 1 lb.

Moment of a force



It is required to find the value of  $x$ .

Sum of clockwise moments : Sum of anti-clockwise moments.


$$2 \times x = 2 \times S$$

$$2 \times x = 10$$

$$x = 5$$

$$5$$

$$x = 2.5 \text{ ft.}$$



When must a 1lb weight be placed between B+C so that the bar is yet kept horizontal?

$$\frac{1}{2}b^2 + 2x \cdot \frac{b+1}{2} \\ \frac{4}{3}x^2 + \frac{1}{2}x = 10 \\ x = 10 \text{ feet.}$$



The weight of the beam is 50 lb. Find the reaction on each support.

$$\begin{aligned} \text{Total force} &= 50 \\ R_1 &= 50 \\ 50 + 500 &= 5x \\ 550 &= 5x \\ x &= 110 \text{ lb.} \end{aligned}$$

Work: force  $\times$  distance. The unit of work in engineering practice is the foot pound.

a) crane raises 650 lbs through 25ft. How much work has been done?

work = force  $\times$  distance  
= 650  $\times$  25 ft-lbs  
= 16250 ft-lbs.

Power: is the rate of doing work, work done per second work  
 $\frac{\text{work}}{\text{time}}$

An aeroplane weighing 6000 lbs rises through a vertical distance of 1000 ft in 5 sec. What power is the aircraft developing during ascent?

$$\frac{6000 \text{ lbs}}{5 \text{ sec}} = 1200 \text{ ft-lbs per sec.}$$

horse power: is the rate of doing 550 ft-lbs of work per second.

H.P. = work done  
Time  $\times$  550

b) A crane raises 550 lbs of cement thru' 10 ft in 2 min. What H.P. is developed?

$$\begin{aligned} \text{Force} &= 550 \\ \text{Distance} &= 10 \text{ ft} \\ \text{Time} &= 2 \text{ min} \\ 550 \times 10 &= 550 \times 10 \times 550 \text{ ft-lbs per sec.} \\ 550 &= 550 \text{ ft-lbs per sec.} \end{aligned}$$

c) A small engine of cyl bore 25 and stroke 5 has an average pressure 25 lb and makes 1000 revs per min. What H.P. is developed? (H.P. is 550 ft-lbs)

$$\begin{aligned} \text{Area} &= \pi r^2 = \pi \times 12.5^2 \text{ in}^2 = 490.87 \text{ in}^2 \\ \text{Volume} &= 490.87 \times 5 \text{ in}^3 = 2454.35 \text{ in}^3 \\ \text{Pressure} &= 25 \text{ lb/in}^2 \\ \text{Force} &= 25 \times 2454.35 = 61360 \text{ lb.} \end{aligned}$$

$$\begin{aligned} \text{Speed} &= 1000 \text{ rev/min} = \frac{1000}{60} \text{ rev/sec} = 16.67 \text{ rev/sec} \\ \text{Work} &= 16.67 \times 61360 = 1022400 \text{ ft-lbs/sec} \\ \text{Power} &= 1022400 \times 550 = 562020000 \text{ ft-lbs/min} \\ &= 562020000 \times \frac{1}{60} \text{ ft-lbs/sec} = 9367000 \text{ ft-lbs/sec} \end{aligned}$$

$$\begin{aligned} \text{Power} &= 9367000 \text{ ft-lbs/sec} \\ &= 9367000 \times \frac{1}{550} \text{ H.P.} = 1700 \text{ H.P.} \end{aligned}$$

d) A boat has a mass of 120 tons + maintains a speed of 20 mph up a slope of 1 in 100. If one slope is 2 miles long, what extra h.p. is required to make the ascent?

$$\begin{aligned} \text{Mass} &= 120 \text{ tons} = 120 \times 2000 \text{ lbs} = 240000 \text{ lbs} \\ \text{Force} &= 240000 \times \frac{1}{100} = 2400 \text{ lbs} \\ \text{Distance} &= 2 \text{ miles} = 2 \times 5280 \text{ ft} = 10560 \text{ ft} \\ \text{Time} &= \frac{10560}{20 \times 5280} = \frac{1}{2} \text{ hr} = 30 \text{ min} \end{aligned}$$

$$\begin{aligned} \text{Power} &= \frac{2400 \times 10560}{30} = 81120 \text{ ft-lbs/sec} \\ &= 81120 \times \frac{1}{550} \text{ H.P.} = 147.5 \text{ H.P.} \end{aligned}$$

$$\begin{aligned} \text{Power} &= 147.5 \text{ H.P.} \\ &= 147.5 \times \frac{1}{550} \text{ H.P.} = 0.268 \text{ H.P.} \end{aligned}$$

1. Mechanical advantage - load  
effort

Eff. ratio - distance moved by effort

Efficiency - work done by load  
load

2. The efficiency is always less than 1.

Efficiency = Work get out  
Work put in



$$\text{MECH. AD} = \frac{L}{E} = \frac{5}{3} = 1\frac{2}{3}$$

$$\text{W.L. RATIO} = \frac{L}{d} = \frac{5}{4} = 1\frac{1}{4}$$

$$\text{EFFICIENCY} = \frac{\text{W.L.}}{\text{E.D.}} = \frac{5 \times 3}{3 \times 2} \\ = \frac{5}{2} = \frac{5}{3}$$

Density - wt. of 1 cu ft of substance

Specific gravity - wt. of substance  
wt. of equal substance of water

Pressure - force per unit area (lb per sq. in.)

Pressure, Force (lb)      Density, Weight (lb)  
Area (sq. in.)              Volume (cu. ft)

Pressure = Wt. x Density (lb./sq. ft.)

Degree of heatness - Temperature.

1. Heat to raise 1 lb. water through 1 deg C.  
1 British Thermal Unit (BTU)

2. Heat to raise 1 lb. water through 1 deg F.  
1 British Thermal Unit (B.T.U.)

### Fuels

#### Hydrocarbons

Mixture Strength - ratio of air / fuel by weight.

1. Chemically correct - ideal, worked out from chemical equation  
(16 : 1 for petrol).

2. Rich mixture - contains less air than 16:1 - 20% rich.

3. Lean mixture - contains more air ... 16:1 - 20% weak.

Density of a gas varies with pressure & varies inversely with temperature.

### Glider Superstition:-

- 1) flame rate  $\rightarrow$  rapid for rich or correct mixture.
- 2) slow for weak mixture.

cause high cyl. temp in ②.

Detonation - spontaneous ignition of part of the charge - due to high cyl. temp + pressure.

- over-fuel - take off. extra fuel for cooling, to prevent detonation.
- 1) Rich ( $\mu = 1$ ) full power, normal running.
  - 2) Weak ( $\mu < 1$ ) causing water small load. Fuel fuel economy.

Energy equation: total energy in a gas is constant.

Potential energy + kinetic energy + heat lost

Volatility - property of evaporating easily.

Calorific heat - heat produced in combustion of 1 kg of fuel

Latent heat of vaporization.

Dew point - should be as low as possible (about  $-50^{\circ}\text{C}$  to  $-60^{\circ}\text{C}$ )

Boiling point can be raised by

- ① Venting (e.g. bengala)
- ② Drying (with filter drier head)

### Requirements of A/c carburetor:

- 1) the liquid fuel must be broken up as far as possible and thoroughly mixed with the air.
- 2) in normal working conditions a constant mixture strength must be maintained.
- 3) a rich mixture must be supplied for idling.
- 4) extra fuel must be supplied during acceleration.
- 5) provision must be made for weakening the mixture when curving at reduced power.
- 6) provision must be made for enriching the mixture for max. power + take off.
- 7) means must be provided for preventing the mixture from becoming richer with increase in altitude.
- 8) ice must be prevented from forming within the carburetor.
- 9) as far as possible the carb. should be automatic, simple to adjust, & robust enough to remain in adjustment under service conditions.

### Filling system:-

Relative Efficiency :-  $\frac{\text{wt. of charge drawn in}}{\text{wt. of charge filling cyl. at S.T.P.}}$

To increase power, we can i.e. by increasing density of charge by supercharging.

Reason for supercharging -

1. To increase the power of an engine of given size + weight.
2. To maintain the same load power up to a high altitude.

Acceleration :- sudden throttle opening causes fuel deposition + the mixture tends to become weak. Prevented by small pump discharge of fuel.

Rated Altitude - that alt. at which full power is obtained at full throttle, with climbing boost + standard RPM.

Supercharger -

1. Fixed gearing.
2. Two-speed gearing.
3. Turbost - driven turbine.

stress when a body is acted upon by a force

These forces are called stress.

Stress is measured as internal force per unit ~~area~~<sup>area</sup>, & so measures the tendency to break.


Measurement of stress - Stress equals  $\frac{\text{applied load}}{\text{area transmitting load}}$ .

strain when a body is acted upon by a force it is deformed. This deformation is called strain.

Measurement of strain, tensile strain :  $\frac{\text{extension}}{\text{original length}}$   
compressive strain :  $\frac{\text{contraction}}{\text{original length}}$ .

Elasticity. If strain disappears when the force is removed the body is elastic.

Relation between stress & strain. Within the elastic limit, stress is proportional to strain. (Hooke's law)  $\frac{\text{stress}}{\text{strain}} = \text{constant}$  (E)



Proof stress - the test piece is subjected to a specified stress for 15 sec. The stress is removed & if there is no permanent deformation the yield point must be higher than the applied stress.

Heat treatment normally applies to high carbon steels.

Steel when heated undergoes several changes of internal structure which affect its properties. The changes in the reverse order take place on cooling only if a cooling is slow. The various changes take place at fairly well defined temp's. Steel should be heated slowly. Do not insert directly into the furnace.

Normalizing:- object,

1. To relieve the stresses set up by previous work, such as forging + bending +
2. To produce a good internal structure.

Method:- Heat to a cherry red heat + allow to cool freely in air.

Annealing:- object,

- > To produce softest possible state when cold.

Method:- heat to a cherry red heat + cool as slowly as possible.  
N.B. The best way is to allow steel + fire to cool together, or to bury steel in the hot ashes.

Hardening:- object:-

- > To produce a maximum hardness

Method:- heat to a cherry red + cool very rapidly by quenching in water or oil, which is less drastic.

The rapid quenching prevents the usual change of structure + traps the steel in a hard intermediate form. This form is only suitable providing


that the steel is not heated above 200°C in use.

Tempering:- object.

- > to relieve excessive brittleness consequent on heating while retaining sufficient hardness.

Method:- Heat to the temp. appropriate to the purpose of the temper + quench.

### Equilibrium Diagram of C-Steel



If more than 1.6% carbon then you get cast iron. Cast iron used for piston rings, because of its high ductility, good wear-resisting, self-lubricating.

> 0.6 to 2.1% carbon is always called low carbon or mild steel

> 0.65 to 1% .... medium ..

> 1% - 1.5% .... high ..

All known as straight steel as there is no alloy present in them.

as the percentage of carbon increases the hardness & tensile strength increases, but the material becomes more & more brittle.

Properties of carbon steel: - all classes of carbon steel contain small quantities of silicon, sulphur & phosphorus. Sulphur causes brittleness & tensile strength. The ill-effects of sulphur eliminated by adding .5 to .7% manganese, which combines with the sulphur to form small sulphide pockets. Phosphorus causes softness.

### Steel gives fatigue resisting properties

Silicon manganese steel for laminated springs.  
<sup>nickel</sup> Silicon chrome steel heat resisting.

Nickel Steel: This strength depends more on their structure & composition than on the hardness produced by special heat treatment as in the case of carbon steel.

3. Increased tensile strength ( $+0.10$  ton per sq.) combined with greater ductility.

3. Increased impact resilience & greater resistance to fatigue.

3. Minimised notch effect giving increased uniformity in strength & toughness throughout large masses.

3. Anti-corrosive properties.

3. Large reduction in weight.

3. Great strength at high temps.

3. Has rapid quenching necessary, owing to above critical change consequently, less risk of cracking.

3. More difficult to produce needs special care & treatment

during manufacture, the more expensive steels cost.

Nickel Ni Molybdenum Mn Vanadium & Cobalt Co tungsten W Chromium Cr Manganese Mn Silicon Si

To increase tensile strength, lower critical point & percentage carbon in the eutectoid. Anti-corrosive, reduces the crystal size, increases the depth of hardening, gives a fine grain, no scaling. (3-5% nickel gives 75% carbon in austenite).

Chromium Contains 18% nickel - is an austemper steel w.r.t. critical point on below mentioned. It has a low coefficient of expansion & is thus used for precision instruments.

Non-magnetic steel contains 25% nickel, to used for shields of polar inductor magnets.

Tensile Nickel Steel = 10 to 12% nickel + 2 to 5% carbon used for case hardening (long working time).

Chromium gives great strength & hardness above up the critical change gives greater depth of hardness in large masses. Raises critical point & produces fine grain i.e. added strength without loss of ductility.

Chromium Steel

- 3. less than 2% chromium if strength & hardness & toughness required.
- 3. 2 to 4% chromium - for permanent magnets.
- 3. 10 to 20% - - - - - Steels.


Nickel Chrome Steel When alloyed together they give increased strength & hardness combined with greater toughness & ductility. These steels must be quenched to avoid brittleness.

Answers for Ex.


1. To bisect an angle



2. To draw a perpendicular to a line




3. To bisect a line



4. Bisect method



5. To draw a parallel to a given line (15° from it)



6. Bisection of angle - line not ruling



7. Perp. At end of line



7. To divide a line into 7 equal parts



8. To draw square on given base line.



9. To construct a regular hexagon. (5 arms compass)




10. Chamfer



Radius of chamfer:  $\frac{1}{2}$

11. Draw circle of radius  $\frac{3}{2}$

To make of circle, draw 1:0



796 to 64

796 to 64

Negative: Natural magnet - lodestone

Artificial .. - Cobalt Steel, Nic & Glass.

Pole: like pole repel

unlike poles attract each other

A magnet is surrounded by

a magnetic field

A magnetic field is made up of a number of lines of magnetic force

The closer together these lines of force lie the stronger is the magnetic field or flux.

Soft iron is easily magnetized + demagnetized + is more permeable to magnetic lines of force than air.

This means that when a piece of soft iron is placed in a magnetic field, the lines of force would enter the iron increase the magnetic flux + the iron becomes a temporary magnet. The iron loses its magnetic properties on being removed from the field.

Electricity: An electric current is a flow of electrons.

All made up of small particles called atoms

Atoms have equal amounts of positive electricity (protons) + negative electricity (electrons)

Conductors of electricity e.g. metals

Will lose electrons when a force is applied. This is called an Electro motive force (EMF) + is measured in volts.

There must be a voltage difference or pressure difference between the terminals of a battery or storage cell, before a current flows through a circuit.

This P.D. is also measured in volts.

Electric current is measured in amperes (amps)

Ohm's law

$$\frac{\text{EMF}}{\text{current}} = \text{constant}$$


$$\frac{E}{I} = R \text{ (Resistance)}$$

Resistance is measured in Ohms

If a current of 1 amp. flows through a conductor under a force of volts the resistance of the conductor is one ohm.

Resistance depends on:

- (1) The kind of metal
- (2) secondly on the length of conductor.
- (3) ... thickness ..







Diagram  
No. 2  
Diagram  
No. 1  
Diagram  
No. 3

Diagram No. 2 is a circle divided into eight equal parts.  
Diagram No. 3 is a circle divided into eight equal parts.

Diagram No. 4 is a circle divided into eight equal parts.

1582196 A.C.2 Wakefield, H.E.  
Hut No 1, A line,  
A Squadron, T.T. Wing,  
R.A.F. Cosford  
Nr. Wolverhampton.  
Staffs.  
Tuesday.

Dear Sheila,

Many thanks for your last letter. You're nearly as bad as Den, it took him two weeks to reply to my letter it took you ten days. I thought you weren't going to write back. Not that it worried me!

At the moment a Mr. Link is giving us a lecture on something or other, I don't know what because I'm not listening.

Two basic Steel types to you - non-magnetic steel.

Stainless (High chromium, high nickel steel) 18% Cr 10% Ni, chrome & nickel  
This is non-resistant to corrosion, is austenitic & so can't be hardened by quenching. Hardened by cold working. Non-magnetic. Very tough & difficult to machine. Tendency to scaling at high temperature & no tendency to harden on cooling. Is used for auto-engine valves.

Chromium is key element in valves steels

Manganese - small quantities up to 1.5% to produce fine grain, it also reduces a tendency for grain structure instabilities. But if increased to impact value greatly gives a tougher steel which is more resistant to vibration.

Tungsten is the base of all high-speed tool steels (i.e. steels which retain their cutting edge to a dull red heat & also permit of

long rapid machining operations in which a straight carbon steel would be completely softened. tungsten raises the critical point (about double).

1% tungsten to straight carbon tool steel gives a fine grain, a tougher material & a much more durable cutting edge. 6% tungsten used for permanent magnet steels. 14% tungsten gives good qualities of tungsten. 21% tungsten gives better qualities.

Silicon is not a metal, but behaves as one in steel alloys. It is present in all steels up to 2% as an impurity, gives fatigue resistance properties. This good quality is increased if alloyed with manganese. Manganese steels are used for laminated springs.

Nickel Chrome gives great heat resisting properties

Nickel Molybdenum Chrome Steel - High carbon steel used for steel rails for rails with the rails ends are hardened by passing with

1. Steel 0.5% C 0.5% Ni 0.5% Cr  
0.5% Mn 0.5% Mo 0.5% Ni 0.5% Cr

2. Brighter 10% Ni 10% Chrome.

3. Duro-chrome Si C molybdenum



This are also used for facing valves, valves, tappets, cams, etc. Vanadium in small quantities up to 2% increases fatigue resistance usually alloyed with tungsten, cobalt & molybdenum added. used in valve springs.

Cobalt gives powerful magnetic properties

Alnico, 5.25 + 10%

gives greater depth of hardness in base makes a tough non-magnetic steel used for steel helmets.





5

5

Dated

21

C

the rock along which completely occupies a valley.  
None of the water of which the valley is  
used to have than any other along these waters.

a  
b  
y  
s  
e  
t  
g  
X  
o